

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	05/12/2015 05/12/2015	Michael Pitta

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_NA0004_01_s _ 2013_4				
Action/Comments					
Inspector Comments: Frank Miller stated that he has a couple copies of the O&M manuals and they are located at the district office.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_NA0004_01_s _ 2013_5				
Action/Comments					
Inspector Comments: LMA stated that most of the emergency flood fight supplies are located at 214 1st St.					

No Photos

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_NA0004_01_s _ 2013_6				
Action/Comments					
Inspector Comments: Frank Miller stated that he and his employees were able to participate in a flood fight training exercise recently with Emergency Services and Yuba County OES.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	05/12/2015 05/12/2015	Michael Pitta

LM Start	0.02	Rating **	M	Issue No.	11
LM End	3.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149855 °	39.164086 °
				-121.600998 °	-121.560835 °
DWR ID	DWR_NA0004_01_s _ 2015_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	0.02	Rating **	M	Issue No.	10
LM End	3.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149856 °	39.164086 °
				-121.600998 °	-121.560836 °
DWR ID	DWR_NA0004_01_s _ 2015_10				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_NA0004\_104\_10\_20150520\_00002.jpg



View of the vegetation on the landside of the levee facing downstream.

LM Start	3.23	Rating **	A/W	Issue No.	1
LM End	3.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.163590 °	39.163590 °
				-121.559495 °	-121.559495 °
DWR ID	DWR_NA0004_01_s _ 2012_1				
Action/Comments					
Repair slope instability. Inspector Comments: This drain pipe has been added to the site on the Corps PI.					

Photo 1 of 1 : SP\_2015\_NA0004\_104\_1\_20150401\_00001.jpg



This site is on the Corps PI.

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	05/12/2015 05/12/2015	Michael Pitta

LM Start	0.01	Rating **	A/W	Issue No.	5
LM End	1.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149439 °	39.134764 °
				-121.601109 °	-121.594121 °
DWR ID	DWR_NA0004_02_s _ 2015_5				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_NA0004\_105\_5\_20150520\_00002.jpg



View of the vegetation on the landside of the levee facing downstream.

LM Start	0.31	Rating **	A/W	Issue No.	6
LM End	0.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.144990 °	39.144990 °
				-121.600576 °	-121.600576 °
DWR ID	DWR_NA0004_02_s _ 2015_6				
Action/Comments					
Note and monitor erosion site.					

No Photos

LM Start	0.49	Rating **	A/W	Issue No.	7
LM End	1.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.142493 °	39.134763 °
				-121.600217 °	-121.594121 °
DWR ID	DWR_NA0004_02_s _ 2015_7				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	05/12/2015 05/12/2015	Michael Pitta

LM Start	0.70	Rating **	M	Issue No.	9
LM End	0.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.139752 °	39.139752 °
				-121.600637 °	-121.600637 °
DWR ID	DWR_NA0004_02_f_2013_9				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Blackberries on waterward levee slope.					

Photo 1 of 1 : SP\_2015\_NA0004\_105\_9\_20150401\_00001.jpg



This photo was taken from the access road going under the 5th street bridge of blackberries growing on the waterward levee slope. Fall 2013.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	05/12/2015 05/12/2015	Michael Pitta

LM Start	0.01	Rating **	M	Issue No.	26
LM End	3.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134858 °	39.172095 °
				-121.593641 °	-121.552278 °
DWR ID	DWR_NA0004_03_s _ 2015_26				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_NA0004\_106\_26\_20150520\_00007.jpg



View of the vegetation on the waterside of the levee facing downstream.

LM Start	0.01	Rating **	M	Issue No.	25
LM End	3.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134858 °	39.172095 °
				-121.593641 °	-121.552278 °
DWR ID	DWR_NA0004_03_s _ 2015_25				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	4.58	Rating **	M	Issue No.	34
LM End	4.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.182347 °	39.182347 °
				-121.542744 °	-121.542744 °
DWR ID	DWR_NA0004_03_f _ 2013_34				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Blackberries on landward levee slope.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---